

NEW

DRIVE SHAFT COUPLINGS


Mackay Part # A5980
Drive Shaft Coupling

Suits
Ford

Suits Ford Falcon BA up to 10/04 (6Cyl Engine)

Bar Code 9313699159807

Replaces OEM 249537



Mackay Part # A5981
Drive Shaft Coupling

Suits
Holden

Suits Holden Commodore VX/VY
V6 Engine 2000-2004
Front & Rear Auto Trans
Front Manual Trans

Bar Code 9313699159814

Replaces OEM 92143593



Mackay Part # A5979
Drive Shaft Coupling

Suits Holden Commodore VT Series I
V8 Engine up to 6/99
Front Manual Trans

Bar Code 9313699159791

Replaces OEM 92141461



MACKAY CONSOLIDATED INDUSTRIES PTY LTD ACN 006 962 401 ABN 72 006 962 401

VICTORIA & SOUTH AUSTRALIA
Head Office, Engineering & Manufacturing
260 Chesterville Road,
PO. Box 1113,
MOORABBIN 3189. VIC, Australia
Telephone: +61 3 9555 6500
Facsimile: +61 3 9276 8882
Email: automotive@mackayrubber.com.au
Website: www.mackayrubber.com.au

NEW SOUTH WALES & QUEENSLAND
PO. Box 655
SEVEN HILLS, NSW 1730. Australia
Telephone: + 61 2 9838 9273
Facsimile: +61 2 9838 9274

WESTERN AUSTRALIA
Automotive Products
Unit 4, 10 Cohn S
CARLISLE, WA 6101 Australia
Telephone: +61 89470 1069
Facsimile: +61 89470 2309
Industrial Products
6 Ledger Road
BALCATT, WA 6021 Australia
Telephone: +61 89344 7388
Facsimile: +61 89345 3910

MACKAY
CONSOLIDATED


Mackay Part # **A4301**

Drive Shaft Coupling

Suits GM Holden / Chevrolet
Commodore VZ & VE inc
Ute's, Lumina, Caprice
Year 09/2004-2009
V6 3.6 litre Engine
Front and Rear
(6 SPD Manual Trans)

Bar Code 9313699143011

Replaces OEM 92148355



Mackay Part # **A4273**

Drive Shaft Coupling

Suits GM Holden / Chevrolet
Commodore VX- VZ inc
Ute's, Lumina, Caprice
Year 2000-2006
V6 Engine
Rear (Manual Trans)
V8 Engine
Front & Rear (Manual & Auto Trans)

Bar Code 9313699142731

Replaces OEM 92143598, 92148358

